



U.S. Department
of Transportation
**Federal Aviation
Administration**

FEDERAL AVIATION ADMINISTRATION – PARTS MANUFACTURER APPROVAL

Aviation Technical Services
3121 109th St. SW
Everett, WA 98204

PMA No. PQ05315NM
Supplement No. 136
Date 11/18/2025

Article Name	Article Number	Approved Replacement for Article Number	Approval Basis and Approved Design Data	Make/TCH Eligibility	Model/Series Eligibility
Gasket – LWR Main Sill, FWD Cargo Door Surround	143A8335-1ATSPMA	143A8335-1	Test and Computations per 14 CFR 21.303 <u>DWG No:</u> 781990-MDL-001 <u>Rev:</u> - <u>Date:</u> 6/12/2025 or later FAA-approved revisions	Boeing	737-700 Series 737-800 Series 737-900ER Series 737-8 737-9
Gasket – LWR Main Sill, AFT Cargo Door Surround	146A8335-1ATSPMA	146A8335-1	Test and Computations per 14 CFR 21.303 <u>DWG No:</u> 781990-MDL-001 <u>Rev:</u> - <u>Date:</u> 6/12/2025 or later FAA-approved revisions	Boeing	737-700 Series 737-800 Series 737-900ER Series 737-8 737-9

-----End of Listing-----

GENERAL NOTES:

Provide minor design changes in a manner as determined by the cognizant FAA certification branch. Process major design changes to drawings and specifications in the same manner as that for an original FAA PMA.

The FAA accepted the instructions for continued airworthiness (ICA) approach for the above articles with their designs. These ICA may refer to those of the respective articles from the holders of type certificates. Otherwise, provide supplemental ICA for differences in the replacement articles. Make referral statements or supplemental ICA readily available per 14 CFR 21.50.

Signature on file
for Gregory S. DiLibero, Manager
West Certification Branch
Compliance & Airworthiness Division
Aircraft Certification Service

for Donald Henchar, Acting Manager
Seattle Certificate Management Section
West Certificate Management Branch
Systems Oversight Division
Aircraft Certification Service